# Agenda Bayshore Gardens Park & Recreation District Board of Trustees Emergency Meeting Wednesday; January 12, 2022 @ 7:45 P.M.



- 2. Call to Order
- 3. Pledge to Flag
- 4. Swimming Pool Repairs
- 5. Adjournment

\*Discussions limited to above topic only.


Pursuant to Section 286.26, Florida Statutes, and the Americans with Disabilities Act, any handicapped person desiring to attend this meeting should contact the District Manager at least 48 hours in advance of meeting to ensure that adequate accommodations are provided for access to the meeting.

Pursuant to Section 286.0105, Florida Statutes, should any person wish to appeal a decision of the Board with respect to any matter considered at this meeting, he or she will need to ensure that a verbatim record of the proceedings is made, including the testimony and evidence upon which the appeal is based.



## **Aqua Leak Detection**

121 Triple Diamond Blvd.
Unit 13
North Venice, FL 34275
(941) 270-6138
www.aqualeaks.com
billing@aqualeaks.com
Inspected by Aqua Leak Detection



## Pool Leak Detection Report

Prepared For:

Bayshore Garden's Park and Recreation

**Property Address:** 

6919 26th Street West Bradenton, FL 34207

Inspected on Fri, Jan 7 2022 at 9:03 AM

# **Table of Contents**

Job Type	3
Equipment	4
Dive Test	5
Plumbing Test	6
Repair Estimate Summary	7
Warranty Information	8

## Job Type

Pool Leak Detection

Job Type:

Pool, Commercial, Basin, Gutters

Pool Leak Detection:

**Pool Leak Detection** 



#### Comment 1:

A Leak Detection is a comprehensive inspection of your pool. There are 3 main components to our inspection.

- 1 Equipment Check:
- -----We observe the equipment, checking for both leaks and functionality.
  - 2 Dive Test:
- ----We swim the pool, visually inspecting the pool surface from the tile line to the main drain in search of leaks, delamination, and broken pool components.
  - 3 Pressure Test:
- -----We apply 15 psi of pressure to the buried pool plumbing. If there is pressure loss, we have the equipment and expertise to locate the broken pipe and can recommend the proper repair based on the leak location.

\*\*\*After the inspection, our team will discuss with you any repairs needed or further direction regarding your pool.

Thank you for the opportunity to care for your pool.

~Aqua Leak Detection

Technician On Site:


Dan E

# Equipment

#### Inspection of Equipment

#### Pool Equipment Photo:





Areas Of Concern: Repairs: No Areas of Concern No Repairs Needed

## Dive Test

Underwater visual inspection of pool surface and features.

Areas Of Concern:

Not Inspected

Repairs:

Not Present

All patchwork is included at no additional cost.

If a leak is too large for standard epoxy patchwork, techs onsite will inform you of what the proper repair procedure and cost will be.

# **Plumbing Test**

All pool plumbing pressurized unless otherwise noted.

Areas Of Concern:

**Gutter line** 

Repairs:

Repairs Needed



#### Comment 2:

Leak found at the bottom of 2 gutter ports. One in zone 5 and one in zone 4. Construction repairs is needed.




Figure 2-1




Figure 2-3




Figure 2-2




Figure 2-4

## Repair Estimate Summary

Some leaks require larger construction repairs.
Below are the quotes for repairs specific to your pool with our standard pricing.

Repairs:

Construction Repairs Are Needed



Comment 3: 2 gutter ports.

Total Repair Quote:

contact office

Optional Repairs:

## Warranty Information



#### Comment 4:

Warranty Information:

- —You have a 30-day warranty on our leak detection service, if your pool is still leaking please call our office within this time period to schedule a warranty leak detection.
- ----30 day warranty on patchwork (typically epoxy patches) from date of leak detection service
- --- 1 year warranty on all construction repairs from date of repair service
- ----Pools are notorious for having more than one leak and our goal on every job is to find every leak, every time.

Our work is guaranteed, so, if a leak is missed we will continue working on your pool until it is leak free.

For more questions, please contact our office at 941.270.6138 Office@AquaLeaks.com



### **Aqua Leak Detection**

121 Triple Diamond Blvd. | Unit 13 | Nokomis, Florida 34275 941-270-6138 | office@aqualeaks.com | www.mypoolleaks.com

п	F	C	IP.	۱F	N	٣:

#### **Bayshore Gardens Park and Recreation**

6919 26th Street West Bradenton, Florida 34207 Phone: 941-755-1912, Office

)22

#### SERVICE ADDRESS:

6919 26th Street West Bradenton, Florida 34207

PRODUCT / SERVICE	DESCRIPTION	оту,	UNIT PRICE	TOTAL
Gutter Port & Under Deck Repair (\$2,200 +)	The price will start at \$2,200 per repair. It could go up depending on if we run into any complications and how much concrete there is.	2	\$2,200.00	\$4,400.00

Total \$4,400.00

This quote is valid for the next 30 days, after which values may be subject to change.

Signature:	Date:	
cignatus.	recte.	